


Utility - Three Phase Transformer Connectors for Underground Use


PBA - Stainless Steel Bolt Assemblies

- * Stainless bolts and washers
- * Silicon bronze nuts

PBA STANDARD DUTY



PBAHD HEAVY DUTY



Catalog Number	Max Clamping Range	Bolt Length
PBA15	0.63	1.50
PBA17	0.88	1.75
PBA20	1.13	2.00
PBA25	1.63	2.50
PBA30	2.13	3.00
PBA35	2.63	3.50
PBA15HD	0.50	1.50
PBA17HD	0.75	1.75
PBA20HD	1.00	2.00
PBA25HD	1.50	2.50
PBA30HD	2.00	3.00
PBA35HD	2.50	3.50

*HD includes two Belleville washers

Consult factory for additional configurations not listed